COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203		SITE NO.: 5ME8557	
		Eligible for National Registeryesno date initials CriteriaABCD	
HISTORIC BUILDING INVENTORY		Contributes to a potential National Register district	
COUNTY: Mesa	CITY: Grand Junction	Eligible for State Registeryesno dateinitials Criteriaabcde Areas of significance:	
HISTORIC BUILDING NAME: Bearce, James, House		Period of significance Initials	
CURRENT BUILDING NAME: Buljung Residence		LOCAL LANDMARK DESIGNATION: [ ] yes [X] no	
ADDRESS: 258 Gunnison Ave., Grand Junction, CO 81501-2312		Date of designation: N/A Designating authority: N/A	
		P.M.: UTE township 1S range:1W SW ¼ of SE ¼ of NW¼ of NW¼ of section 14	
OWNER NAME & ADDRESS: Maria Buljung, 258 Gunnison Ave., Grand Junction, CO 81501-2312		UTM REFERENCE-12 Easting: 710420 Northing: 4327610	
		USGS QUAD NAME: Grand Junction	
		Year: 1962; photorevised 1973 [X] 7.5' [ ] 15'	
STYLE: Vernacular Wood Frame		Block: 35 Lot(s): 19 and 20 Addition: Year of addition:	
BUILDING TYPE:		[X] original location [] moved	
MATERIALS: Concrete Foundation - Wood/Asbestos Frame - Asphalt Shingle Roof		Date of moves(s):	
		PRESENT USE: Domestic	
STORIES: 2	SQUARE FOOTAGE: 1151	DATE OF CONSTRUCTION- estimate: 1910 actual: Source of information: Tax Assessor's Records	
PLAN SHAPE:	north arrow	ARCHITECT: Unknown	
	Li	Source of information:	
		BUILDER/CONTRACTOR: Unknown	
		Source of information:	
		ORIGINAL OWNER: L.J. Bolen	
2		Source of information: Lot and Block Books	
		ASSOCIATED BUILDINGS- [ ] yes [X ] no	
		Туре:	

ARCHITECTURAL DESCRIPTION: Two story, front gable roof. Concrete foundation is light tan. One story, side gable wing project from the east elevation. Carpet covered concrete steps, with a metal railing on the east side of the facade, lead to a sunporch/entry with shed roof. Asbestos shingle siding on porch half-wall and a half height, squared Tuscan, comer post. Porch facade has three, double hung, wood sash windows, six-over-six. East side of porch has three sash windows, one-over-one. Metal frame storm porch door. Windows around house are double hung, wood sash, one-over-one, with wood frame storm windows. All windows on house have wood plank shutters. Light tan asbestos shingle siding. Porch posts, window frames and surrounds, shutters and raking cornices are light tan. Wood frame storm windows are brown. Green composition shingle roof.


Landscaped yard. Dirt yard next to street with two raised plant beds. Grass front and back yards. Mature pine tree in front yard. Three trimmed evergreens and rose bushes along facade. Trimmed evergreens and rose bushes, and chain-link fence along west side of lot. Backyard enclosed by light tan picket fence. Mature tree in backyard.

PHOTOGRAPHS (include photographs showing each side of building and any associated buildings)				
Film roll no.: 46 Negative no.: 8	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction			
CONSTRUCTION HISTORY (include description and o or modifications not noted in Assessor's records.	dates of major additions, alterations, or demolitions):	Storm windows and siding. Additional construction		
HISTORICAL BACKGROUND (discuss important persons and events associated with this building): Listed as built in 1905, there are no improvements at this location until 1910, when the house was owned by Lou J. Bolan (widow of Henry) through 1920, when she moved to Spokane, Washington. William Utterman, owner of the Wm. Utterman Seed Company, owned the house ca. 1925-1927, and lived there 1925-1935. Rosalie and Jas. C. Bearce, an engineer with the Denver and Rio Grande Railway, rented the house ca. 1937-1942, and owned it through at least 1947.				
INFORMATION SOURCES (be specific): Plat Map, Appraisal Card, Lot and Block Books, Grand Junction City Directories.				
SIGNIFICANCE (check appropriate categories)		THEME(S):		
Architectural significance: [] represents the work of a master [] possess high artistic value [X] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district			
National Register eligibility: Individual [] yes [X] no Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture	Contributes to a potential district: []yes [ X]no District name:			
Period of significance: 1910				
STATEMENT OF SIGNIFICANCE (briefly justify the significance checked above): House has undergone various updates, including asbestos siding and shutters. Although not eligible for the National Register, this house may contribute to a local register.				
INVENTORY COMPLETED BY: Museum Group Staff		DATE: 5/31/96		
AFFILIATION: Museum of Western Colorado		Рноке: (970) 241-9117		
ADDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2		



```
258 Gunnison Ave., Grand Junction, Mesa Co, CO
2945-142-23-010 05/14/1996
Roll 46 Frame 8 View S Dir NW
5mE8557
```

24



258 Gunnison Ave., Grand Junction, Mesa Co, CO 2945-142-23-010 05/14/1996 Roll 46 Frame 8 View S Dir NW 5m€3557

de,

2