OAHP1403 wp2


- 14

COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation		SITE NO.: 5ME8562
1300 Broadway Denver, CO 80203 HISTORIC BUILDING INVENTORY		Eligible for National Registervesno date initials CriteriaABCD Contributes to a potential National Register district vesno district name:
County: Mesa	CITY: Grand Junction	Eligible for State Registeryes no date initials Criteriaabcde Areas of significance:
HISTORIC BUILDING NAME: Rathbone, Fred and Lylah, House		Period of significance Needs data date initials
CURRENT BUILDING NAME: ADDRESS: 217 Grand Ave., Grand Junction, CO 81501		LOCAL LANDMARK DESIGNATION: [] yes [X] no Date of designation: N/A Designating authority: N/A
		P.M.: UTE township: 1S range:1W NE ¼ of NE ¼ of NW¼ of SW¼ of section 14
OWNER NAME & ADDRESS: Betty J. Kempton, 2805 Mesa Ave., Grand Junction, CO 81501-4915		UTM REFERENCE-12 Easting: 710335 Northing: 4327180
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Classic Cottage		Block: 79 Lot(s): 5 and W1' of 6 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved Date of moves(s):
MATERIALS: Concrete Foundation - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic
		PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 572	DATE OF CONSTRUCTION- estimate: 1904 actual: Source of Information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
	$\langle \rangle$	Source of information:
		BUILDER/CONTRACTOR: Unknown
		Source of information:
		ORIGINAL OWNER: E. Blaine
		Source of information: Lot and Block Books
		ASSOCIATED BUILDINGS- [X] yes [] no
		Type: Shed

Concrete steps lead to sunporch/entry situated on post. Porch glazing consists of one, fixed pane, r flush with three diamond lights. Windows around window with transom. Double arched, wood louve and corner post, raking cornice and cornice return on ridge.	s, and fishscale shingles in gable are white. Salme	al siding on half-wall. Squared half height corner Idows. Porch has metal storm door. Main door is		
PHOTOGRAPHS (include photographs showing each	side of building and any associated buildings)			
Film roll no.: 42 Negative no.: 18	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction			
CONSTRUCTION HISTORY (include description and dates of major additions, alterations, or demolitions): Porch enclosed. Additional construction or modifications not noted in Assessor's records.				
improvements until 1904. The E. Blaine Estate is Ooca, a laborer at Holly Sugar, lived in the house the renter, ca. 1926; Margaret and Earl G. Miller, a	a switchman with the Denver and Rio Grande Railw			
INFORMATION SOURCES (be specific): Plat Map, Ap	praisal Card, Lot and Block Books, Grand Junction	City Directories.		
SIGNIFICANCE (check appropriate categories)		THEME(S):		
Architectural significance: [] represents the work of a master [] possess high artistic value [X] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district			
National Register eligibility: Individual [] yes [X] no Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:			
Period of significance: 1904				
	ficance checked above). One of the few houses r onal Register, this house may contribute to a local r			
INVENTORY COMPLETED BY: Museum Group Staff		DATE: 5/31/96		
AFFILIATION: Museum of Western Colorado		PHONE: (970) 241-9117		
ADDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2		



217 Grand Aue, Grand Junction, Mesa Co, CO 2945-143-02-003 Roll 42, Frame 18 View N Dies Smc 8562



217 Grand Aue., Grand Junction, Mesa Co, CO 2945-143-02-003 Roll 42, Frame 18 View N Dies Smc 8562