
OAHP1403.wp2

COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203 HISTORIC BUILDING INVENTORY		SITE NO.: 5ME8568	
		Eligible for National Registeryesno date initials CriteriaABCD Contributes to a potential National Register district yesno district name:	
County: Mesa	CITY: Grand Junction	Eligible for State Registeryesno date Initials Criteriaabcde Areas of significance:	
HISTORIC BUILDING NAME: Hards, Dora, House		Period of significance Needs data date initials	
CURRENT BUILDING NAME: Schurr Residence		LOCAL LANDMARK DESIGNATION: [] yes [X] no	
ADDRESS: 747 Colorado Ave., Grand Junction, CO 81501-3514		Date of designation: N/A Designating authority: N/A	
		P.M.: UTE township: 1S range:1W NE ½ of NW ½ of SW½ of SE½ of section 14	
OWNER NAME & ADDRESS: Klem L. Schurr, 747 Colorado Ave., Grand Junction, CO 81501-3514		UTM REFERENCE-12 Easting: 711140 Northing: 4326740	
		USGS QUAD NAME: Grand Junction	
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'	
STYLE: Vernacular Wood Frame		Block: 128 Lot(s): E23' of 16 and all of 17 Addition: Year of addition:	
BUILDING TYPE:		[X] original location [] moved	
		Date of moves(s):	
MATERIALS Concrete Pier Foundation - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic PRESENT USE: Domestic	
STORIES: 1	Square footage: 1505	DATE OF CONSTRUCTION- estimate: 1907 actual: Source of information: Tax Assessor's Records	
PLAN SHAPE	horth arrow	ARCHITECT: Unknown	
	\rightarrow	Source of information:	
		BUILDER/CONTRACTOR: Unknown	
ſ		Source of information:	
		ORIGINAL OWNER: Mamie (Minnie) Frazier	
-5		Source of information: Lot and Block Books	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
5 C		ASSOCIATED BUILDINGS- (X) yes [] no	

ARCHITECTURAL DESCRIPTION: One story hip roof with cross gables. Concrete foundation. Concrete steps. Enclosed wraparound porch, with hip roof, extends across the facade. East three fourths of the porch facade has vertical varnished wood siding with a ribbon of three large single light windows. West quarter of the porch has siding and windows like the main body of the house. Door is paneled with a large light. Windows are mostly replacement pairs of single light, metal frame sliding windows. On the east elevation is a projecting bay with shed roof, and narrow, double hung wood sash windows, one-over-one. Gray, wood shingle siding. Red clapboard on porch base. Window surrounds, frieze, fascias and the gable face are white. Short additions are on the three elevations. Green composition shingle roof. The boxed eaves have fascias. Front gable is pedimented with a kick. The gable face is white false bevel wood with a Palladian window. Gable peak is filled with a triangular, wood louvered ventilator. Lawn. Planter of small stone rubblework is across the east facade. Two arborvitae flank the steps. Roses and trees are on the parking. Wood fence around the back yard. One car garage at rear may now be living space. The roof and siding are the same as the house.				
PHOTOGRAPHS (include photographs showing each side of building and any associated buildings)				
Film roll no.: 44 Negative no.: 24	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction			
CONSTRUCTION HISTORY (include description and dates of major additions, alterations, or demolitions): Enclosed porch, siding, windows. Additional construction or modifications not noted in Assessor's records.				
HISTORICAL BACKGROUND (discuss important persons and events associated with this building): The house, constructed ca. 1907, was first owned by C. E. and Mary Lance. Minnie (Mamie?) Frazier was the absentee owner, ca. 1908-1921. The initial occupants are not identified. Dora and James Hards, a barber, were the owners/occupants ca. 1922 to at least 1947; and the occupants, ca. 1926-1937. Gertrude and Wilbur B. Hards, a dentist, were also occupants, ca. 1922. Renters ca. 1940-1946 included a clerk, a bookkeeper, and a railroad brakeman.				
INFORMATION SOURCES (be specific): Plat Map, Appraisal Card, Lot and Block Books, Grand Junction City Directories. Sanborn Fire Insurance Maps: 1904-1907.				
SIGNIFICANCE (check appropriate categories)		THEME(S):		
Architectural significance: [] represents the work of a master [] possess high artistic value [X] represents a type, period, or method of construction	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district			
National Register eligibility: Individual [] yes [X] no Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:			
Period of significance: 1907				
STATEMENT OF SIGNIFICANCE (briefly justify the significance checked above): Formerly a mirror image of 741 Colorado, next door. They both have been remodeled out of similarity to each other. Although not eligible for the National Register, this house may contribute to a local register.				
INVENTORY COMPLETED BY: Museum Group Staff		Date: 5/31/96		
AFFILIATION: Museum of Western Colorado		PHONE: (970) 241-9117		
ADDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2		



747 Colorado Ave., Grand Junction, Mesa Co, CO 2945-144-29-010 05/14/1996 Roll 44 Frame 24 View N Dir SE SmE3568 ÷.



 747 Colorado Ave., Grand Junction, Mesa Co, CO

 2945-144-29-010
 05/14/1996

 Roll 44 Frame 24 View N Dir SE

 5ME8568