
COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203		SITE NO.: 5ME7904
		Eligible for National Registeryesno
		date initials CriteriaABCD
HISTORIC BUILDING INVENTORY		Contributes to a potential National Register district
		yesno district name:
		Eligible for State Registeryesno
COUNTY: Mesa	Citry: Grand Junction	date initials Criteriaabcde
		Criteriaabcde Areas of significance:
HISTORIC BUILDING NAME: Hall, Frank, House		
		Period of significance initials
CURRENT BUILDING NAME: Mickelsen Residence		LOCAL LANDMARK DESIGNATION: [] yes [X] no
		Date of designation: N/A
ADDRESS: 850 Hill Ave., Grand Junction, C	O 81501-3232	Designating authority: N/A
		P.M.: UTE township: 1S range:1W SE ½ of SE ½ of NW½ of NE½ of section 14
OWNER NAME & ADDRESS: Kalvin C. Mickelsen, 850 Hill Ave., Grand Junction, CO 81501-3232		UTM REFERENCE-12 Easting: 711300
		Northing: 4327720
		USGS QUAD NAME: Grand Junction
		Year: 1962; photorevised 1973 [X] 7.5' [] 15'
STYLE: Bungalow		Black: 26
		Lot(s): 20 - 22
		Addition: Year of addition:
		rear of addition;
BUILDING TYPE:		[X] original location [] moved
		Date of moves(s):
MATERIALS: Mud Sill Foundation - Wood Frame - Asphalt Shingle Roof		HISTORIC USE: Domestic
		PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 1272	DATE OF CONSTRUCTION- estimate: 1926 actual:
		Source of information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
	1	Source of Information.
ું હ	U	Source of Information:
		BUILDER/CONTRACTOR: Unknown
		Source of information:
[]		
6		ORIGINAL OWNER: Eugena K. Hall
·/	[Source of information: Lot and Block Books
		ASSOCIATED BUILDINGS- [X] yes [] no
		Type: 2 Car Garage
	108	

ARCHITECTURAL DESCRIPTION: One story with side hip on gable. Battered foundation. Concrete steps and stoop with brick plers. Concrete coping on piers. Gabled portico over stoop has curved celling and is supported by two long, curved wall braces. Siding on portico gable face. Front door is paneled and has four vertical lights. Windows are double hung wood sash, five and four vertical lights over one. Sunroom is a short wing on the east elevation with a hip on gable roof. Fenestration on three sides is ribbons of casements, one-over-one. Storm windows on all windows around house. Yellow narrow lapped siding. Window and door surrounds, foundation, comer boards, side gables with board and batten siding, bargeboards and rafter ends are brown. Brown composition shingle roof. Exposed rafter ends. Shaped bargeboard tails. Curved metal finials on ridges. Brick chimney on east slope. Two large arborvitae bushes obscure the east facade and a large cedar on the west facade. Row of arborvitae on east lawn. Lattice fence on east lawn, chain link fence on west lawn. Elm tree in parking area. Two car garage at rear with flat roof, stepped parapets, yellow false bevel siding, and folding paneled door. Also, large two car garage with alley access is a later addition. Front gable, gray composition shingle roof, concrete block construction and contemporary metal door.				
PHOTOGRAPHS (include photographs showing each side of building and any associated buildings)				
Film roll no.: 19 Negative no.: 18	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction			
CONSTRUCTION HISTORY (include description and dates of major additions, alterations, or demolitions): Roof materials changed from wood shakes to asphalt in 1988. Additional construction or modifications not noted in Assessor's records.				
HISTORICAL BACKGROUND (discuss important persons and events associated with this building): Eugena and Frank R. Hall, Kelly-Hall Investment Agency, were the original owners of the house. They resided in it from its construction in ca. 1926 until ca. 1966.				
INFORMATION SOURCES (be specific): Plat Map, Appraisal Card, Lot and Block Books, Grand Junction City Directories, 1981 Historic Survey of Grand Junction, Obituary Index. Grand Junction <u>Dally Sentinel</u> Newspaper, 21 Dec 1963, p1.				
SIGNIFICANCE (check appropriate categories)		THEME(S):		
Architectural significance: [] represents the work of a master [] possess high artistic value [X] represents a type, period, or method of construction National Register eligibility: Individual [] yes [X] no	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district			
Criteria: [] A [] B [] C [] D Area(s) of significance: Architecture	Contributes to a potential district: []yes [X]no District name:			
Period of significance: 1926				
STATEMENT OF SIGNIFICANCE (briefly justify the significance checked above): A good bungalow on a large lot. The wall braces under the portico are large and distinctive. The new siding is narrow lapped and appropriate, although the board and batten appearance of the foundation and gables is not. Although not eligible for the National Register, this house may contribute to a local register.				
INVENTORY COMPLETED BY: Museum Group Staff		DATE: 3/29/96		
AFFILIATION: Museum of Western Colorado		PHONE: (970) 241-9117		
ADDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2		

0

Ł





850 Hill Ave., Grand Junction, Mesa Co, CO 2945-141-15-015 1/29/1996 Roll 19 Frame 18 View S Dir N/NE 5ME7904