

2945-143-22-024

COLORADO HISTORICAL SOCIETY
Office of Archaeology and Historic Preservation
1300 Broadway Denver, Colorado 80203

HISTORIC BUILDING INVENTORY RECORD

project name: Grand Junction Downtown Survey
county: Mesa city: Grand Junction
state ID no. SME 7224 temporary no.
current building name: First National Bank Bulding Entrance
address: 3rd & Colorado Parking Lot, Grand Junction, CO 81501
owner:
township: 1S range: 1W section: 14, NW 1/4, SW 1/4
historic name:
USGS quad name: Grand Jct., CO 1962 N3900-W10830 X 7.5' 15'
district name:
block: lot(s) addition: City
yr. of addition
film roll by: Marty Alexandroff no.
negative nos. 6837-20
location of negatives: City of Grand Junction
date of construction _____ estimate 1910 actual
source: 1981 Historic Survey of City
use: commercial present commercial historic
condition: X excellent ___ good ___ fair ___ deteriorating
extent of alterations: ___ minor ___ moderate X major
describe: Building fragment from demolition of structure at 464
Main. Moved from original site of NW/c 5th and Main
style: Romanesque
stories: 1
 original X moved date(s) of move:

materials: brick

Square footage:

National Register Eligibility:

Individual: yes no

Contributing to district: yes no

local landmark designation: _____ name _____ date

associated buildings? yes type:

if inventoried, list ID nos.

architectural description: This is the original 1910 entrance to the First National Bank Building (464 Main, Dalby, Wentland & Co.). It is a one story brick structure with an arched entry with circular projection at top with the word "Bank".

architect: unknown

source:

original owner: unknown

source:

builder/contractor: unknown

source:

theme(s): Plateau Country/commerical

construction history: (description, names, dates, etc. relating to major additions or alterations to original structure)
Moved to present site from corner of 5th and Main. Date unknown.

historic background (discuss important persons and events associated with this structure)

This structure is located within the original platted area of Grand Junction and was a entrance structure to the original First National Bank Building built in 1910.

significance: (check appropriate categories and briefly justify below)

_____ architectural significance:
_____ represents the work of a master

_____ possesses high artistic values

_____ represents a type, period or method of construction

_____ historic significance:
_____ associated with significant persons
_____ associated with significant events or patterns
_____ contributes to an historic district

statement of significance:

Contributing

This structure is located within the original platted area of Grand Junction and was part of the original First National Bank Building.

references (be specific)

surveyed by: Marty Alexandroff
date: July, 1994

affiliation: Winter & Company

