COLORADO CULTURAL RESOURCE SURVEY

OSAC/DHP; 1300 Broadway, Denver, CO 80203

NOT FOR FIELD USE

DET. ELIG.

	IMPORTANT: CO RESOURCE PLUS HISTORICAL/AR
I. IDENTIFICATION	1: 1)Resource 1
3)Resource Name	
5)Category: Arch.	Site_, Hist./
6) (For Arch. site)	In a District:
II. LOCATION: 7)1	Cownship IN
Section 32; P.M	i. UTE PM
9)USGS QUAD	Grand-Junctio
portion of Quad. C	
11)Dimensions	mX
13)UTM Reference:	


INVENTORY RECORD

IMPORTANT: COMPLETE THIS SHEET FOR EACH RESOURCE PLUS EITHER AN ARCHAEOLOGICAL OR HISTORICAL/ARCHITECTURAL COMPONENT FORM.
I. IDENTIFICATION: 1)Resource No2)Temp. No2701-321-00-067
3)Resource Name4)Project NameHSI: Gnd. Jct. Vicinity
5)Category: Arch. Site, Hist./Archit. Structure X, Hist./Archit. District
6)(For Arch. site)In a District:yes_no ^X ;Name;
II. LOCATION: 7) Township IN ; Range IW. ; 4 of 12 of NE 2 of 2 of 2 of
Section 32; P.M. UTE PM . 8)County Mesa
9)USGS QUADGrand_Junction;7.5_15_;DateAttach photocopy
portion of Quad. Clearly show site. 10)Other maps
11)DimensionsmXm 12)Areasq.m(+4047=)acres
13)UTM Reference: (One UTM centered on resource may be given for resource under 10 acres) A
C;mE;mN. D;mE;mN.
14)Address 773 24 Rd. Lot Block Addition
III. MANAGEMENT DATA: 15)Field Assessment: EligibleNot EligibleNeed Data
16)Owner/Address Sharon D. Tuchscher 245-1503
17)Gov't Involvement: CountyStateFederalPrivate: Agency
18)Disturbance:none_light_moderate_heavy_total_;Explain
19) Threats to Resource: Water Erosion_Wind Erosion_Animal Activity_Neglect_Vandalism
RecreationConstruction;Comments
20)Management Recommendations
V. REFERENCE: 21)State/Fed. Permit Nos81-7
22)Photo Nos. AG: 32.35 23)Report Title HISTORIC STRUCTURE INVENTORY
23)Report litle
24)Recorder 25)Recording Date 8/4/1981

26)Recorder Affiliation WESTERN HERITAGE CONSERVATION 27)Phone No425-1262

Resource No.

V. SKETCH MAF: Map all features and show the boundaries of the resources. Show all major topographic features, permanent modern features, and vegetation zones as appropriate Give names of features, streets and addresses if known. Provide scale, key and direction.



28)Location/Access:

29)Boundary Description:

as shown on assessor map.

30) Boundary Justification:

ownership.

3

	1300 Bro	oadway, Denver, CO	0 80203
ARCHITECTURAL/HISTO	RICAL COMPONENT FORM		
ECORDING HISTORIC STRUCT	JRES AND DISTRICTS. USE SEP	RECORD FORM FOR	
		e V	
		-	
Altered <u>x</u> Explain:	porch screened in: minor	change	
			5
Date 1913	13) Architect/Builder		
Style(s) Mission sty	/le		
res/Surroundings:leaded	glass windows		
, 동작 전 생기 등기		die se	5
	21 - Carl 40 - Carl		<u> </u>
and off of the second	: 'NY 2017 - 2017 - 2017		
1 Peterstin I. Vec No.	Tinknown Fynlains		
ai rotentiai; ies no			5.5 * *
CTTVITIES. Ver the recour	ce type (ie: house harm s	bed school chur	ch.etc)
to the cultura	1 activity theme and sub-th	eme category asso	ciated
with it,			
		-	
Rural		4	
Dwelling			
			ĺ
	t n a fill c		
	<pre>XTANT: USE IN CONJUNCTION DECORDING HISTORIC STRUCTURES DING STRUCTURES LOCATED W 2701-321- 5ME2919 2) Temp No 2 24 Rd 2 Condition: Good Fa Moved Date(s) of Altered Explain: 3 11) Building Materials Date Date Date Style(s) Mission sty mes/Surroundings: res/Surroundings: added contential: Yes No CTIVITIES: Key the resour to the cultura with it. Residential Rural</pre>	ARCHITECTURAL/HISTORICAL COMPONENT FORM_ TANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY F ECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEE DING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES. <u>SME2019</u> 2) Temp No	TANT: USE IN CONJUNCTION WITH THE GREEN INVENTORY RECORD FORM FOR TECORDING HISTORIC STRUCTURES AND DISTRICTS. USE SEPARATELY FOR DING STRUCTURES LOCATED WITHIN DISTRICT BOUNDARIES. 2701-321-00-065) Name



Frame Number35Roll NumberA6Facade OrientationE

IV. SIGNIFICANCE: Assess whether or not the resource has any historical or architectural merit by checking appropriate categories and justifying below. Include any relevant historical data.

20) Architectural Significance:

21) Historical Significance:

Represents work of a master

Possesses high artistic values

* Represents a type, period, or method of construction

Associated with significant persons Associated with significant events or patterns

Contributes to the significance of an historic district

The house was built by Archie and Ema Thrailkill, in 1913. The Thrailkills traveled to California every winter due to the poor health of their son. Mrs. Thrailkill was impressed by the California Spanish farmhouses and she patterned her new house after these. The house is constructed with a lathe base and a stucco finish.

The Thrailkills came to Colorado in 1895. They were originally farmers in Missouri. The family rented an immigrant car to move their family possessions and livestock to the Grand Valley. They purchased 40 acres of land before 1900 at the site of the current residence. They lived in a shabbily constructed house prior to the construction of the stucco residence. The major crops the Thrailkills raised were apples and strawberries.

This mission style farm house possesses a high degree of integrity and is a style very rare in Mesa County.

22) List Any Associated Cultural Group:

V. REFERENCES:

SharonHISTOCHECHER, TRUGHERWICHYFYFYFYFYR Road, Grand Junction, Colorado. Interview, 20 November, 1981. Mrs. Edith Thrailkill, 756 24 Road, Grand Junction, Colorado. Interview, 20 November, 1981.

RECORDER



UNITED STATES EPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

