COLORADO HISTORICAL SOCIETY Office of Archaeology and Historic Preservation 1300 Broadway Denver, CO 80203		SITE NO.: 5ME7836
HISTORIC BUILDING INVENTORY		dateinitials CriteriaABCD Contributes to a potential National Register district yesno district name:
COUNTY: Mesa	CITY: Grand Junction	Eligible for State Registeryesno dateinitials Criteriaabcde Areas of significance;
HISTORIC BUILDING NAME: McCleneghan, William, House		Period of significance
CURRENT BUILDING NAME: Rosen Residence		LOCAL LANDMARK DESIGNATION: [ ] yes [X] no
ADDRESS: 1059 Chipeta Ave., Grand Junction, CO 81501-3350		Date of designation: N/A Designating authority: N/A
		P.M.: UTE township: 1S range:1W NW ¼ of SE ¼ of SE¼ of NE¼ of section 14
OWNER NAME & ADDRESS: Daniel M. Rosen, 1059 Chipeta Ave., Grand Junction, CO 81501-3350		UTM REFERENCE-12 Easting: 711575 Northing: 4327410
		USGS QUAD NAME: Grand Junction
STYLE: Bungalow		Year: 1962; photorevised 1973 [X] 7.5' [ ] 15'
		Block: 65 Lot(s): 15 and 16 Addition: Year of addition:
BUILDING TYPE:		[X] original location [] moved
MATERIALS: Concrete Foundation - Wood Frame/Brick - Asphalt Shingle Roof		Date of moves(s): HISTORIC USE: Domestic
		PRESENT USE: Domestic
STORIES: 1	SQUARE FOOTAGE: 1248	DATE OF CONSTRUCTION- estimate: 1910 actual: Source of information: Tax Assessor's Records
PLAN SHAPE:	north arrow	ARCHITECT: Unknown
6		Source of information:
	2	BUILDER/CONTRACTOR: Unknown
		Source of information:
		ORIGINAL OWNER: Wm. E. and Alice Dudley
		Source of information: Lot and Block
	58	ASSOCIATED BUILDINGS- [X] yes [] no
		Type: Garage

one-over-one and six-over-six, and have storm w siding. Brown sills on porch half-walls, brown ca composition shingle roof with a brick chimney on Soil is banked around the foundation and cov tree, rocks and lava in parking area.	are wood shingled. Front door is paneled and indows. A shallow projecting bay window with a pitals on porch columns. Brown window and do ridge.	t walk. Fir and pampas grass on east lawn. An ash
PHOTOGRAPHS (include photographs showing each	n side of building and any associated buildings)	
Film roll no.: 18 Negative no.: 16	Photographer: Carolyn Howard Location of negatives: City Of Grand Junction	
CONSTRUCTION HISTORY (Include description and da modifications not noted on Assessor's Records.	ates of major additions, atterations, or demoittion	ns): Storm windows. Additional construction or
Ciece and william E. Dudley. Clara and will McCle	negnan, occupations unknown, were the next o , residing in it until ca. 1932. From ca. 1933-19 , Administration. A printer for the Daily Sentinel	42, they rented it to a piano tuner and then to a farm was the occupant ca. 1946, and Home Loan the
SIGNIFICANCE (check appropriate categories)		THENE(0)
Architectural significance: [] represents the work of a master [] possess high artistic value [X] represents a type, period, or method of construction National Register eligibility:	Historical significance: [] associated with significant person(s) [] associated with significant event [] associated with a pattern of events [] contributes to an historic district Contributes to a potential district:	THEME(S):
	[]yes [ X]no District name:	
Period of significance: 1910		
STATEMENT OF SIGNIFICANCE (briefly justify the signific the area. Although not eligible for the National Reg	cance checked above): One of the numerous ister, this house may contribute to a local registe	Bungalows with transitional Arts and Crafts features in er.
INVENTORY COMPLETED BY: Museum Group Staff		DATE: 3/29/96
AFFILIATION: Museum of Western Colorado		PHONE: (970) 241-9117
ADDRESS: PO Box 20000-5020, Grand Junction, Colorado 81502-5020		PROJECT NAME: Grand Junction Historic Resources Survey, Phase 2



1059 Chipeta Ave. Grand Junction, Mesa Co, CO 2945-141-32-008 5ME7836 01/12/1996 Roll 18 Frame 16 View N Dir SW 5ME7836



1059 Chipeta Ave. Grand Junction, Mesa Co, CO 2945-141-32-008 5ME7836

ŝ

a phile